



Black Diamond™

STOP USE UNTIL INSPECTED

Speed Harnesses Product Safety Bulletin

Name of Product: Black Diamond Focus Speed, Gym Speed, Momentum Speed, Vario Speed and Wiz Kid



Focus Speed



Gym Speed



Momentum Speed




Vario Speed



Wiz Kid



Correct



Incorrect

Salt Lake City, Utah (June 29, 2006)—Black Diamond Equipment, Ltd. voluntarily announced a recall of Black Diamond Speed Harnesses—Focus Speed, Gym Speed, Momentum Speed, Vario Speed and Wiz Kid—for possibility of incorrectly threaded waist and/or leg loop buckles. Affected units were sold from December 2005 through June 2006. Black Diamond has received one report from a customer with no injuries.

Incorrectly threaded buckles can loosen causing inadequate protection. The buckle is incorrectly threaded if you can see the center bar of the top buckle. All harnesses with incorrectly threaded buckles must not be used and should be immediately returned to Black Diamond for a free replacement.

For help in identifying the affected harnesses and/or for instructions to return, please contact Black Diamond Equipment at (801) 278-5533 or e-mail: climb@bdel.com.

**Black Diamond Warranty Center
c/o Speed Harness Recall
2084 East 3900 South, Salt Lake City, UT 84124**